

Eagle Copters Ltd. 823 McTavish Road NE Calgary, AB T2E 7G9 Canada

FLIGHT MANUAL SUPPLEMENT

1003-FM-001

Inlet Barrier Filter Installation

EAGLE 407HP MODELS

SH16-9

Sections 1-4 of this document comprise the approved Flight Manual Supplement. Compliance with Section 1, Limitations is mandatory. Section 0 is Unapproved and is provided for information only.

This supplement must be attached to the approved Flight Manual when the Inlet Barrier Filter is installed per 1003-MI-001. The information contained herein supplements the information in Flight Manual Supplement FMS-E407-789-1. For limitations, procedures and performance not contained in this document, consult Flight Manual Supplement FMS-E407-789-1.

Transport Canada

Transports Canada

AIRCRAFT CERTIFICATION

DIVISION

APPROVED

Approved Date 20

YY-MM-DD

Prepared By:

V. Seib

Mechanical Designer

Checked By:

H. Siemens

Mechanical Designer

Released By:

D. Shepherd Chief Engineer

LOG OF AMENDMENTS

Rev. No.	Pages Revised	Revised By and Date	Approved By Inserted By and Date	Date Inserted
Α	None	V. Seib 16.03.17	Museum	
		1	2016.03.30	-

SECTION 0 - INTRODUCTION

Eagle Copters has developed a Supplemental Type Certificate (STC) for the Eagle 407HP to install an inlet barrier filter. The Inlet Barrier Filter (IBF) assembly is installed inside the inlet cowl assembly as shown in Figure 1. The IBF is held into place via the modified engine inlet floor and the top cowl. All air flow into the engine will pass through the IBF thereby providing the engine with air that is free from possibly harmful particulates.

A pressure differential sensor is installed as part of the system and will alert the pilot via an annunciator in the cockpit (see Figure 2) should the filter become blocked. With the INSTR LT rotary switch in the OFF position, the IBF annunciator is set to bright. When the INSTR LT is in any position other than the OFF position, the brightness of the IBF annunciator is controlled by the position of the BRT/DIM switch. To determine the blockage of the filter, the pressure difference between the upstream and the downstream side of the filter is measured. The pressure differential switch is set to a predetermined value.

Once the annunciator illuminates, the pilot can activate the T-handle on the LH side of the center pedestal (see Figure 3) to open the mechanical bypass door (see Figure 4) allowing the airflow to bypass the filter thus permitting unfiltered air to enter the engine. Unfiltered air is drawn through the space around the transmission / main rotor mast primarily though the vertical opening towards the main rotor. The bypass door will remain open until the helicopter lands and a maintenance action is carried out to remove and clean the inlet barrier filter and close the bypass door.

A filter maintenance aid (see Figure 5) inside the air inlet cowl can be viewed by opening the lower LH access door pre/post flight to establish the condition of IBF.




FIGURE 1 - INLET BARRIER FILTER INSTALLATION IN INLET COWL



FIGURE 2 - IBF ANNUNCIATOR



FIGURE 3 – BYPASS DOOR T-HANDLE

• COPYRIGHT © 2016 BY EAGLE COPTERS LTD •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM EAGLE COPTERS LTD.




FIGURE 4 - INLET COWL WITH BYPASS DOOR




FIGURE 5 - FILTER MAINTENANCE AID

COPYRIGHT © 2016 BY EAGLE COPTERS LTD •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM EAGLE COPTERS LTD.

SECTION 1 - LIMITATIONS

1.3 TYPES OF OPERATION

The snow deflector kit (206-708-208) shall be installed when conducting flight operation in falling and/or blowing snow with the IBF installed.

Takeoff with "IBF" annunciator illuminated is PROHIBITED.

MAR 3 0 2016

TCCA Approved:

(DATE)

SECTION 2 – NORMAL PROCEDURES

2.3 PREFLIGHT CHECK

2.3B EXTERIOR CHECK

- 1. AIR INLET Free of accumulated debris, snow, ice, slush, etc.
- 2. IBF Free of accumulated debris, snow, ice, slush, etc.
- 3. IBF Filter material in good condition
- 4. BYPASS DOOR Closed
- 5. FILTER MAINTENANCE AID Reads lower than 7.

NOTE

During flight operators with snow deflector kit installed the Filter Maintenance Aid (FMA) will not provide accurate readings and should not be used. Upon removal of the snow deflectors, reset the FMA.

2.4 INTERIOR AND PRESTART CHECK

- 1. IBF ANNUNCIATOR Not illuminated
- 2. BYPASS DOOR T-HANDLE Closed

2.7 BEFORE TAKEOFF

IBF ANNUNCIATOR – Not illuminated

2.8 TAKEOFF

1. IBF ANNUNCIATOR - Not illuminated

TCCA Approved:

MAR 3 0 2016

(DATE)

SECTION 3 – EMERGENCY/MALFUNCTION PROCEDURES

INLET BARRIER FILTER WARNING

- INDICATIONS:
 - 1. IBF annunciator illuminates and/or unexplained increase in engine MGT/N₁
- PROCEDURE:
 - 1. Reduce power and speed.
 - 2. IBF ANNUNCIATOR Extinguishes,
 - 3. Continue flight at reduced power/speed.

If the IBF annunciator does not extinguish,

4. BYPASS DOOR T-HANDLE - Pull

NOTE

Button on T-Handle must continue to be depressed as handle is pulled outwards.

- 5. DOOR OPEN ANNUNCIATOR Illuminated
- 6. IBF ANNUNCIATOR Extinguishes
- 7. Continue flight
- 8. Service filter prior to next flight.

If the IBF annunciator does not extinguish and/or DOOR OPEN annunciator fails to illuminate,

- 9. Monitor engine instruments
- 10. Engine parameters within limits Land as soon as practical
- 11. Engine parameters out of limits Land as soon as possible
- 12. Service filter prior to next flight

TCCA Approved: MAR 3 0 2016

Table 3-1. CAUTION (YELLOW) ANNUNCIATOR LIGHTS

CAUTION ADVISORY SYSTEM MESSAGE	FAULT CONDITION	CORRECTIVE ACTION
IBF	The Inlet Barrier Filter has become dirty / blocked with debris.	 Reduce power and speed Activate the Bypass Door handle to open the Bypass Door. The IBF annunciator should extinguish and the DOOR OPEN annunciator should illuminate.

Table 3-2. ADVISORY (BLUE) ANNUNCIATOR LIGHTS

CAUTION ADVISORY SYSTEM MESSAGE	FAULT CONDITION	CORRECTIVE ACTION	
DOOR OPEN	The Bypass Door handle has been activated (pulled).	No Pilot corrective action required	

TCCA Approved: MAR 3 0 2016

COPYRIGHT © 2016 BY EAGLE COPTERS LTD •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM EAGLE COPTERS LTD.

SECTION 4 – PERFORMANCE

4.5 HOVER CEILING

- 1. Up to 12,000ft PA, no change to Hover Ceiling Charts presented in FMS-E407-789-1
- 2. Above 12,000ft PA, no change to Hover Ceiling Charts presented in FMS-E407-789-1 as long as aircraft shows +15°C margin on the Power Assurance Check within the last 24 hours. Otherwise, add 287 lbs to the aircraft weight to obtain Hover Ceiling.
- 3. If snow deflector kit (206-708-208) is installed, add 350 lbs to aircraft weight to obtain Hover Ceiling at any altitude in addition to the penalties described in items 1 and 2 above

4.7 CLIMB AND DESCENT

4.7A CLIMB

- 1. Up to 12,000ft PA, no change to Rate of Climb Charts presented in FMS-E407-789-1
- 2. Above 12,000ft PA, no change to Rate of Climb Charts presented in FMS-E407-789-1 as long as aircraft shows +15°C margin on the Power Assurance Check within the last 24 hours. Otherwise, add 287 lbs to the aircraft weight to obtain Rate of Climb.
- 3. If snow deflector kit (206-708-208) is installed, add 350 lbs to aircraft weight to obtain Rate of Climb at any altitude in addition to the penalties described in items 1 and 2 above.

TCCA Approved:

MAR 3 0 2016

(DATE)